




G02 - Flagstone flooring in poor/fair condition



G06 -Mix of stone setts and modern concrete flooring in very poor condition



G08 - Flagstones in very poor condition




G10 - Stone setts in very poor condition



G12 - Mix of flagstones and stone setts in very poor condition



G20 & G21 - Mix of flagstone and brick in very poor condition



G23 - Modern concrete flooring in poor condition over flagstones



G24 - Mix of modern concrete and stone setts in poor condition

Adjacent Properties and Boundaries are shown for illustrative purposes only and have not been surveyed unless otherwise stated.
All areas shown are approximate and should be verified before forming the basis of a decision.
Do not scale other than for Planning Application purposes.
All dimensions must be checked by the contractor before commencing work on site.
No deviation from this drawing will be permitted without the prior written consent of the Architect.
The copyright of this drawing remains with the Architect and may not be reproduced in any form without prior written consent.
Ground Floor Slabs, Foundations, Sub-Structures, etc. All work below ground level is shown provisionally. Inspection of ground condition is essential prior to work commencing.
Reassessment is essential when the ground conditions are apparent, and redesign may be necessary in the light of soil conditions found. The responsibility for establishing the soil and sub-soil conditions rests with the contractor.

Rev	Date	Description	Initials
PROJECT		6150 Tottenham House The Old Stables	
TITLE:		Existing Ground Floor Finishes - Images	
SCALE:		NTS	
DATE:		December 2025	
DRAWING No:		6150/CE-119	
DRAWN BY:		EH	