

Architectural floor plan of a building with structural annotations. The plan shows rooms 20 and 22, a roof void, and various structural elements like floorboards, cupboards, and fireplaces. Red hatched areas indicate decayed joists and lintels. Red arrows point to specific areas with annotations:

- ALLOW FOR OPENING UP WORKS TO ENABLE STRUCTURAL ENGINEER TO REVIEW FLOOR STRUCTURE.
- ALLOW FOR REMOVAL OF FLOORBOARDS TO ASSESS EXTENT OF JOIST DECAY.
- ALLOW FOR OPENING UP WORKS AND TEMPORARY PROPPING TO EXPOSE EXTENT OF LINTEL DECAY.
- ALLOW FOR OPENING UP WORKS TO EXPOSE EXTENT OF DECAY TO EAST WINDOW LINTELS.
- ALLOW FOR TEMPORARY PROPPING AND OPENING UP WORKS TO REPLACE FAILED LINTEL.
- EXTENT OF DECAY TO WINDOW MULLION TO BE ASSESSED ON SITE BY STRUCTURAL ENGINEER.
- OPEN UP TO ALLOW FOR STRUCTURAL ENGINEER TO REVIEW DECAYED LINTEL.

Scale: 0 1 2 3 MTR. 1:100