

Jasmine Cottage
33 Oxford Street, Ramsbury, Wilts, SN8 2PS

Photographic record of the existing metal frame perspex glazed conservatory.



PHOTO 1 – REAR ELEVATION SHOWING EXISTING CONSERVATORY



PHOTO 2 – REAR ELEVATION SHOWING EXISTING CONSERVATORY



PHOTO 3 – REAR ELEVATION SHOWING HOW THE EXISTING CONSERVATORY CLASHES WITH THE FF WINDOW



PHOTO 4 – REAR ELEVATION SHOWING HOW THE EXISTING CONSERVATORY DISSECTS THE GF WINDOW



PHOTO 5 – REAR ELEVATION SHOWING HOW THE EXISTING CONSERVATORY DISSECTS THE GF WINDOW



PHOTO 6 – REAR ELEVATION SHOWING HOW THE EXISTING CONSERVATORY DISSECTS THE Ff WINDOW



PHOTO 7 – REAR ELEVATION SHOWING THE INSIDE OF THE EXISTING CONSERVATORY



PHOTO 8 – REAR ELEVATION SHOWING HOW THE EXISTING CONSERVATORY SITS ON THE REAR OF THE COTTAGE