

Date: 03/03/26
Drawing No. Photos
Driveway Lower Moor
cottage SP35LB

All pictures at Lower Moor Cottage



1.
Outside tap
turned on to
full capacity
demonstrating
permeable tar-
mac with no
pooling



2.
Aco drain at toe of drive as found 24/02/26 demonstrating
broad leaf tree debris



3.
Emptied of debris and cleaned Aco drain at toe of drive demonstrating running outlet at lowest point



4.
Picture of Highway in Salisbury direction. For clarity



5.
Picture of
Highway in
Tisbury di-
rection. For
clarity