




Proposed Works:

Ensure the flue is cleaned and not blocked.

Remove the later mantle shelf and make good the surround to match existing.

S.07 Fireplace.

Early C 19th painted wooden, bracketed surround with a later added mantle shelf.
Plain chamfered stone kerb.
Raised cement inner hearth.
Floral patterned ceramic slips over terracotta base layer.
Fire brick lining



Revisions : Rev Date

Scale : NTS

Drawn : CP

Date : December 2025

Drawing No.

1306.D.21

Drawing : Detail Specifications for repair works to:

Fireplace - S.07