

Existing door





Current walls and ceiling
which is all staying the
same but getting boarded
over

A photograph of a cluttered storage room. The walls are made of grey stone blocks, and the ceiling is made of dark wooden beams. The floor is concrete. Various items are scattered on the floor, including a large yellow water container, a blue plastic bin, a white metal cage, a white cabinet, a black jacket, a pair of black shoes, and several cardboard boxes. Some boxes are labeled 'FRAGILE'. A red squiggly line is drawn on the wooden ceiling beam. The text 'Existing walls and ceiling which will be boarded up and plastered' is overlaid on the image.

Existing walls and ceiling
which will be boarded up
and plastered



Existing garage door which
is staying and getting
boarded up inside so no
external changes