N

Bramble scrub with managed hedge adjacent roadside.

Bramble scrub / hedgerow.

Scrub area.

Bramble scrub hedgerow.

Bramble scrub.

Possible conflict with trees from attenuation pond

Possible conflict with trees from attenuation pond

Tree stump

Bramble scrub.

Bramble scrub.

Possible conflict with trees from attenuation pond

FUGGLESTONE ROAD

ASHLEE ROAD

ASHLEE DRIVE

GREEN CLOSE

COOKS CLOSE

LIMES CLOSE

SHADEHOUSE CLOSE

ASHMORE CRESCENT

Symbol Guide

- Root Protection Area
- Canopy Spread
- Tree Position, (colour represents retention category)
- Tag Number

BS5837:2012 - Tree Category

- Category A Trees High Quality
- Category B Trees Moderate Quality
- Proposed Tree for Removal (Dashed Canopy)
- Category C Trees Low Quality
- Category U Trees Poor Quality/Remove
- Line of Protective Fencing

Client:
Persimmon Homes West

Agent:
Richard McWilliam

Date:
December 2014

Scale:
1:1500 @ A0

Project Name:
Fugglestone Road,
Salisbury,Wilts, SP2 9AE

Drawing Title:
Tree Protection Plan
(Plan 2 of 2)

Drawing Number:
141210-1.1-FR-TPP-NC

Treework Environmental Practice
Monarch House
1-7 Smyth Road
Bedminster
Bristol
BS3 2BX

Tel: 01172 440012
Web: www.treeworks.co.uk
e.mail: info@treeworks.co.uk