


1055 – EXISTING PHOTOGRAPHIC RECORD OF SECOND FLOOR




01 – Stair Landing



02 – Stair Landing
Services Cupboard




03 – Stair Landing
Services Cupboard



04 – Stair Landing
Services Cupboard



05 – Stair Landing
Services Cupboard



06 – Stair Landing
Services Cupboard



07 – Stair Landing
Services Cupboard



08 – Stair Landing
Partition Wall & Door




09 – Stair Landing
Partition Wall & Door



10 – Bedroom Entrance & Rooflight



11 – Rooflight & Door to Eaves Storage




12 – Door to Balcony from Bedroom



13 – Bedroom from Entrance



14 – Bedroom from Entrance



15 – Rooflight & Door to Eaves Storage



16 – Bedroom from Ensuite



17 – Bedroom from Entrance




18 – Bedroom from Entrance



19 – Ensuite



20 – Ensuite




21 – Ensuite



22 – Ensuite



23 – Ensuite



24 – Ensuite



25 – Existing Truss retained with partition and door set behind to form Ensuite




26 – Existing Truss retained with partition and door set behind to form Stair landing



27 – Services to voids




28 – Services to voids



29 – Services to voids



30 – Storage Area Ensuite End



31 – Storage Area Ensuite End



32 – Storage Area Ensuite End