


Replacement Windows and Doors at 43-45 London Road, Chippenham, Wiltshire, SN15 3AJ

All windows and doors are rotten. Many don't open at all and some open with a wedge, but there are no working sashes. None of the windows have ledges that protect from the weather and some have no ledges at all.





1) Shower Room – window to front of house



2) Bedroom 1 side? (front of house)




3) Kitchen



4) Lounge



5) Utility room



- 6) Downstairs toilet in utility room. This swings open on a single screw.



- 7) Bedroom 2 (first floor, back left when looking from the garden)
M's room – to change to a casement window



- 8) Landing - to change back to a casement window





- 9) Bedroom 3 - to change back to a casement window (first floor, back right when looking from the garden) H's room



- 10) Aga room – to change back to a casement window



11) Dining room – to change back to a casement window



12) Bathroom – looking from front and then right-hand side of house





Privacy Level 4

For example
Pilkington **Contora**™

We are wanting to use obscured glass for the bathroom windows. This one is from <https://www.pilkington.com/en-gb/uk/householders/decorative-glazing>

13) Bedroom 1 from front



14) Bedroom 4 – right side of house when looking from the front.
To be changed back to a casement window






15) Bedroom 5 – left side of house when looking from the front. To change back to a casement window



Front doors – 45 and 43



17



16