




Building Survey Legend:	
<i>SHt 1.00</i>	Still Height from FFL
<i>SHt 2.12</i>	Head Height from FFL
<i>SL 51.03m</i>	Still Level from defined datum.
<i>HL 52.82m</i>	Head Level from defined datum.
<i>Susp CHt: 2.00</i>	Suspended Ceiling Height from FFL
<i>Struct CHt: 3.00</i>	Structural Ceiling Height from FFL
<i>Susp Ceil: 30.00m</i>	Suspended Ceiling Level from datum.
<i>Struct Ceil: 31.00m</i>	Structural Ceiling Level from datum.
<i>IFL: 100.00m</i>	Internal Floor Level (General).
<i>+100.00m</i>	External Floor Level (Specific).
<i>Insertion</i>	Insertion Point for overview drawings.

	Insertion Point	Insertion Point
Incoming Services		
		

[illegible]

Rev	Date	Description	Drawn	Q. Ref.
-----	------	-------------	-------	---------



greenhatch

group

• Topographical Surveys • Site Engineering • Utility / CCTV Surveys • Bathymetric Surveys	• Measured Building Surveys • 3D Laser Scanning • 3D Render & BIM Models • Areas, Lease & Fire Plans
--	---

Rowan House
Duffield Road
Little Eaton
De21 5DR

Tel (01332) 830044 Fax (01332) 830055
 admin@greenhatch-group.co.uk
www.greenhatch-group.co.uk

St Albans	Newcastle	Central London
Unit 1, The Courtyard	24 Riverside Studios	27 Cornwall Terrace Mess
Alban Park	Ameyrath Road	Regents Park
St Albans	Newcastle	London
Hertfordshire	Unit Newcastle-U-Tyne	NW11 5SL
UK G4	NE4 7TE	
Tel (01272) 654481	Tel (01272) 736391	Tel (020) 2241806

CLIENT
Chippenham Town Council

PROJECT

**Chippenham Town Hall
High Street
Chippenham**

TITLE **Existing Second Floor
Plan**

SCALE A1@ 1: 100	DATE 01/08/2022
DRAWN JM	QUALITY REF G14415

Level datum	GPS
Grid orientation	GPS
Job number	44158

Drawing No.	Rev.
44158_04_P	0

Comments

This plan should only be used for its original purpose. Greenhatch Group accepts no responsibility for this plan if supplied to any party other than the original client.

All dimensions should be checked on site prior to design and construction.

Some services may have been omitted due to parked vehicles.

Drainage information (where applicable) has been visually inspected from the surface and therefore should be treated as approximate only.

© F&G