

Proposed Internal Alterations & Mezzanine Floor

at

Calne Free Church
Church Street, Calne
Wiltshire
SN11 0HS

Site Photographs – Internal

Prepared for

Calne Free Church

Ref number:	25005 SP02 Site Photographs – Internal
By:	Dale Roberts
Date:	May 2026
Revision:	
Status:	PLANNING



Fig 1 – Large Hall: False Ceiling Concealing Victorian Roof Structure



Fig 2 – Large Hall: SE Wall & Windows (Proposed Restoration)



Fig 3 – Large Hall: Overall Character, Scale & False Ceiling



Fig 4 – Large Hall: North East End Showing Existing Layout



Fig 5 – Large Hall: View Toward Store Rooms (Proposed Staircase & Lift Location)



Fig 6 – Large Hall: South End



Fig 7 – Entrance Hall: Existing External Door & Lobby



Fig 8 – Entrance Hall: Corridor to Toilet Block



Fig 9 – Male Toilet: Existing Urinal Cubicle



Fig 10 – Male Toilet: Existing Washbasin Area




Fig 11 – Male Toilet: WC Cubicle (No Wheelchair Accessible Facility)




Fig 12 – Female Toilet: Existing WC Cubicles



Fig 13 – Female Toilet: Existing Washbasin Area



Fig 14 – Small Hall: General View & Existing False Ceiling



Fig 15 – Small Hall: SE Wall & Kitchen Area



Fig 16 – Narrow Doorway (800mm) with 3 Steps – Accessibility Barrier



Fig 17 – Roof Void / Toilet Block: Victorian Timber Roof Structure




Fig 18 – Roof Void / Toilet Block: Truss Detail



Fig 19 – Roof Void / Large Hall: King Rod Scissor Trusses (Hidden by False Ceiling)



Fig 20 – Roof Void / Large Hall: Truss Configuration & Scissor Bracing



Fig 21 – Roof Void / Large Hall: Blocked Stone Mullioned Window (Proposed Restoration)



Fig 22 – Truss Detail: Rafter with Stop-Chamfered Victorian Carpentry



Fig 23 – Truss Detail: King Rod & Scissor Bracing Showing Wrought Iron Construction