

BS5837 Report

Enims

Salisbury Hospital

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
G01	Not identified (Not identified)	Tree	1 stems Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good Small young trees which make up part of the shelterbelt.	C1	No RPA.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	No Photo
G02	Not identified x6 (Not identified)	Group 6 trees	6 stems, avg.(mm): 250 Spread (m): 5N, 5E, 5S, 5W Life Stage: Semi Mature Rem. Contrib.: 10+ Years	Crown: Fair Stem: Ivy Basal Area: Good A group of approximately 6 ash in decent condition/minor ash dieback.	B1	Area: 137 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
G03	Not identified (Not identified)	Group	1 stems Rem. Contrib.: <10 years	A group of 4 ash which are either dead or dying.	C1	No RPA.		Other Reference: Physiological Condition: Decline Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
G07	Elder x5 (Sambucus nigra)	Group 5 trees	Height (m): 7 5 stems, avg.(mm): 140 Spread (m): 1.5N, 1.5E, 1.5S, 1.5W Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Trees located at the end of the parking spaces as boundary screening.	C2	Area: 71 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Fair Distance1: Distance2: You customise: Public Amenity Value: Low Inspection Limitations: Bat Habitat:	No action required.	 No Photo

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
G10	Common ash x8 (<i>Fraxinus excelsior</i>)	Group 8 trees	Height (m): 8 8 stems, avg.(mm): 160 Spread (m): 2N, 2E, 2S, 2W Life Stage: Young Rem. Contrib.: 30+ Years	Group of ash trees within the shelterbelt.	C2	Area: 52 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Fair Distance1: Distance2: You customise: Public Amenity Value: Low Inspection Limitations: None Bat Habitat:	No action required.	
T01	Purple maple (<i>Acer palmatum 'Atropurpureum'</i>)	Tree	Height (m): 9 Stem Diam(mm): 250 Spread (m): 2.5N, 2.5E, 3.5S, 1.5W Lowest Branch (m): 2(E) Life Stage: Young Rem. Contrib.: 20+ Years	Crown: Fair Stem: Fair Basal Area: Good Dead wood in canopy.	B1	Radius: 3.0m. Area: 28 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T02	Cherry plum (<i>Prunus cerasifera</i>)	Tree	Height (m): 4.5 Stem Diam(mm): 110 Spread (m): 2N, 1.5E, 1.5S, 0.5W Lowest Branch (m): 1(S) Life Stage: Young Rem. Contrib.: 10+ Years	Crown: Good Stem: Fair Basal Area: Fair	C1	Radius: 1.3m. Area: 5 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T03	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 6.5 Stem Diam(mm): 120 Spread (m): 2N, 2E, 2S, 2W Lowest Branch (m): 1.5(N) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 1.4m. Area: 6 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T04	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 6.5 Stem Diam(mm): 120 Spread (m): 2N, 2E, 2S, 2W Lowest Branch (m): 1.5(N) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 1.4m. Area: 6 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T05	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 6.5 Stem Diam(mm): 120 Spread (m): 2N, 2E, 2S, 2W Lowest Branch (m): 1.5(N) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 1.4m. Area: 6 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T06	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 7.5 Stem Diam(mm): 160 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 2(S) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 1.9m. Area: 11 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T07	Hazel (<i>Corylus avellana</i>)	Tree 10 stems	Height (m): 7.5 10 stems, avg.(mm): 80 Spread (m): 4N, 2E, 4S, 2W Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Crown: Good Stem: Good Basal Area: Good Group of hazel stems within the shelterbelt.	C1	Radius: 3.0m. Area: 28 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T08	Field maple (<i>Acer campestre</i>)	Tree	Height (m): 12 Stem Diam(mm): 160 Spread (m): 3N, 3E, 3S, 3W Lowest Branch (m): 7(E) Life Stage: Young Rem. Contrib.: 20+ Years	Crown: Good Stem: Fair Basal Area: Good Tree located within the shelterbelt.	B1	Radius: 1.9m. Area: 11 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T09	Field maple (<i>Acer campestre</i>)	Tree	Height (m): 10 Stem Diam(mm): 110 Spread (m): 2N, 2E, 2S, 2W Life Stage: Young Rem. Contrib.: 10+ Years	Crown: Fair Stem: Fair Basal Area: Good Tree located within the shelterbelt.	C1	Radius: 1.3m. Area: 5 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T10	Field maple (<i>Acer campestre</i>)	Tree	Height (m): 10 Stem Diam(mm): 110 Spread (m): 2N, 2E, 2S, 2W Life Stage: Young Rem. Contrib.: 10+ Years	Crown: Fair Stem: Fair Basal Area: Good Tree located within the shelterbelt.	C1	Radius: 1.3m. Area: 5 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T11	Black elder (<i>Sambucus nigra</i>)	Tree 7 stems	Height (m): 8 7 stems, avg.(mm): 110 Spread (m): 2N, 1.5E, 1.5S, 2W Lowest Branch (m): 2(N) Life Stage: Young Rem. Contrib.: 10+ Years	Crown: Fair Stem: Fair Basal Area: Fair Dead wood in canopy.	C1	Radius: 3.5m. Area: 38 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T12	Common ash (<i>Fraxinus excelsior</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 3N, 3E, 3S, 3W Lowest Branch (m): 3(N) Life Stage: Semi Mature Rem. Contrib.: 10+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T13	Crack willow (<i>Salix fragilis</i>)	Tree 4 stems	Height (m): 12 4 stems (mm): 100, 100, 100, 80 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 3(N) Life Stage: Young Rem. Contrib.: 20+ Years	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 2.3m. Area: 17 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T14	Pedunculate oak (<i>Quercus robur</i>)	Tree	Height (m): 9 Stem Diam(mm): 190 Spread (m): 3N, 3E, 3S, 2.5W Life Stage: Young Rem. Contrib.: <10 years	Crown: Poor Stem: Poor Basal Area: Fair Tree showing major decline and apical dieback. Not within limb falling distance or the car park	C1	Radius: 2.3m. Area: 17 sq m.		Other Reference: Physiological Condition: Decline Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T15	Cotoneaster (<i>Cotoneaster sp.</i>)	Tree 6 stems	Height (m): 5.5 6 stems, avg.(mm): 120 Spread (m): 5N, 5E, 5S, 5W Life Stage: Young Rem. Contrib.: 20+ Years	Group of Willow-leaved cotoneaster.	C1	Radius: 3.5m. Area: 38 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T16	Crab apple (<i>Malus sylvestris</i>)	Tree 2 stems	Height (m): 5 2 stems (mm): 140, 120 Spread (m): 2N, 2E, 2S, 2W Lowest Branch (m): 2(S) Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Crown: Good Stem: Fair Basal Area: Good Located close to the fence.	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T17	Common walnut (<i>Juglans regia</i>)	Tree	Height (m): 6 Stem Diam(mm): 150 Spread (m): 2N, 2E, 2S, 2W Life Stage: Young Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good Tree located within the field border.	C1	Radius: 1.8m. Area: 10 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T18	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 8 Stem Diam(mm): 130 Spread (m): 2N, 2E, 1.5S, 1.5W Life Stage: Young Rem. Contrib.: 10+ Years	Crown: Fair Stem: Fair Basal Area: Good Dead wood in canopy.	C1	Radius: 1.6m. Area: 8 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T19	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 3N, 3E, 3S, 3W Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Crown: Fair Stem: Good Basal Area: Good Minor dead wood in canopy.	C1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T20	Goat willow (<i>Salix caprea</i>)	Tree	Height (m): 7 Stem Diam(mm): 170 Spread (m): 2.5N, 2.5E, 2S, 2W Lowest Branch (m): 2(W) Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.0m. Area: 13 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T21	Sycamore (<i>Acer pseudoplatanus</i>)	Tree	Height (m): 7.5 Stem Diam(mm): 190 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Life Stage: Mature Rem. Contrib.: <10 years	Crown: Poor Stem: Fair Basal Area: Fair Large amount of apical dieback and retrenchment.	C1	Radius: 2.3m. Area: 17 sq m.		Other Reference: Physiological Condition: Poor Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T22	Hornbeam (<i>Carpinus betulus</i>)	Tree	Height (m): 8 Stem Diam(mm): 150 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Life Stage: Young Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 1.8m. Area: 10 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T23	Crack willow (<i>Salix fragilis</i>)	Tree	Height (m): 12 Stem Diam(mm): 200 Spread (m): 3N, 3E, 3S, 3W Life Stage: Young Rem. Contrib.: 20+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.4m. Area: 18 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T24	Pedunculate oak (<i>Quercus robur</i>)	Tree	Height (m): 8 Stem Diam(mm): 150 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 4(W) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 1.8m. Area: 10 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T25	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 6 Stem Diam(mm): 180 Spread (m): 2N, 2E, 2S, 2W Lowest Branch (m): 2.5(N) Life Stage: Young Rem. Contrib.: 20+ Years	Crown: Fair Stem: Fair Basal Area: Good Epicormic growths on the stem.	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Low Inspection Limitations: None Bat Habitat:	Pre construction: Remove Planting stakes and ties During construction: Remove Epicormic growths	No Photo
T26	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 6 Stem Diam(mm): 180 Spread (m): 2N, 2E, 2S, 2W Lowest Branch (m): 2(S) Life Stage: Young Rem. Contrib.: 20+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	No Photo
T138	Norway maple (<i>Acer platanoides</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 3N, 3E, 3S, 3W Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Crown: Fair Stem: Good Basal Area: Good Minor dead wood in canopy.	C1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Fair Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T139	Common ash (<i>Fraxinus excelsior</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 3N, 3E, 3S, 3W Lowest Branch (m): 3(N) Life Stage: Semi Mature Rem. Contrib.: 10+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T140	Pedunculate oak (<i>Quercus robur</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 3N, 3E, 3S, 3W Lowest Branch (m): 3(N) Life Stage: Semi Mature Rem. Contrib.: 10+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	No Photo

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T141	Elder (<i>Sambucus nigra</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 3N, 3E, 3S, 3W Lowest Branch (m): 3(N) Life Stage: Semi Mature Rem. Contrib.: 10+ Years	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T142	Hornbeam (<i>Carpinus betulus</i>)	Tree	Height (m): 8 Stem Diam(mm): 130 Spread (m): 3N, 3E, 3S, 3W Lowest Branch (m): 3(N) Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 1.6m. Area: 8 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Low Inspection Limitations: Bat Habitat:	No action No action	
T143	Pedunculate oak (<i>Quercus robur</i>)	Tree	Height (m): 8 Stem Diam(mm): 150 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 4(W) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	C1	Radius: 1.8m. Area: 10 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	No Photo
T144	Common ash (<i>Fraxinus excelsior</i>)	Tree	Height (m): 8 Stem Diam(mm): 170 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 4(W) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.0m. Area: 13 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	No Photo
T145	Goat willow (<i>Salix caprea</i>)	Tree	Height (m): 8 Stem Diam(mm): 150 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 4(W) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 1.8m. Area: 10 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	
T146	Pedunculate oak (<i>Quercus robur</i>)	Tree	Height (m): 8 Stem Diam(mm): 150 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 4(W) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 1.8m. Area: 10 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T147	Hornbeam (<i>Carpinus betulus</i>)	Tree	Height (m): 12 Stem Diam(mm): 180 Spread (m): 2.5N, 2.5E, 2.5S, 2.5W Lowest Branch (m): 4(W) Life Stage: Semi Mature Rem. Contrib.: 41	Crown: Good Stem: Good Basal Area: Good	B1	Radius: 2.2m. Area: 15 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Distance1: Distance2: You customise: Public Amenity Value: Inspection Limitations: Bat Habitat:	No action No action	