






Figure 3. Walker's and Ponting's analyses













Figure 5. Received chronological development









Figure 13. Implied and observed interventions






Figure 14. Summary of historic survival: ground floor



- Late 19th - 20th C fabric
- Mid 19th C fabric
- 15th - Early 19th C fabric

Figure 15. Summary of historic survival: first floor