

BS5837 Report

Enims

Salisbury Hospital western car park

Retention Category	No. trees
A	3
B	5
C	1

Rem. Contrib.	No. trees
20+ Years	6
30+ Years	3
Not Recorded	3

Total	9
-------	---

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
H01a	Mixed species (Mixed species)	Hedge	Height (m): 3.5 1 stems Spread (m): 1N, 1E, 1S, 1W Life Stage: Young Rem. Contrib.: 20+ Years	Small and young mixed native hedgerow. No arboricultural concerns.	C2	Area: 134 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Low Inspection Limitations: None Bat Habitat:	No action required.	
T01	Sycamore (Acer pseudoplatanus)	Tree 2 stems	Height (m): 8 2 stems (mm): 230, 270 Spread (m): 4N, 4E, 4S, 4W Crown Clearance (m): 3 Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Tree located as a feature within the car parking area between the buildings. Minor dead wood in the canopy.	B2	Radius: 4.3m. Area: 58 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Moderate Inspection Limitations: None Bat Habitat:	No action required.	
T02	Sycamore (Acer pseudoplatanus)	Tree	Height (m): 8 Stem Diam(mm): 280 Spread (m): 3N, 4E, 4S, 4W Crown Clearance (m): 3 Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Tree located on grass lawn. Minor dead wood in the canopy.	B2	Radius: 3.4m. Area: 36 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Low Inspection Limitations: None Bat Habitat:	No action required.	
T03	Sycamore (Acer pseudoplatanus)	Tree	Height (m): 16 Stem Diam(mm): 560 Spread (m): 5N, 5E, 6S, 6W Crown Clearance (m): 5 Life Stage: Mature Rem. Contrib.: 30+ Years	Tree located on grass area between car parking spaces. Good leaf canopy cover.	A1	Radius: 6.7m. Area: 141 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Good Inspection Limitations: None Bat Habitat:	No action required.	

Ref.	Species	Full Structure	Measurements	Survey Notes	Retention Category	RPA	Comments	Measurements2	Recommendations	Photo
T04	Common beech (<i>Fagus sylvatica</i>)	Tree	Height (m): 16 Stem Diam(mm): 560 Spread (m): 5N, 7E, 6S, 4W Crown Clearance (m): 2 Life Stage: Mature Rem. Contrib.: 30+ Years	Tree located on grass area between car parking spaces. Good leaf canopy cover.	A1	Radius: 6.7m. Area: 141 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Good Inspection Limitations: None Bat Habitat:	No action required.	
T05	European lime (<i>Tilia x europaea</i>)	Tree	Height (m): 15 Stem Diam(mm): 470 Spread (m): 5N, 5E, 5S, 5W Crown Clearance (m): 5 Life Stage: Mature Rem. Contrib.: 30+ Years	Tree located on grass area between car parking spaces. Good leaf canopy cover. Minor dead wood in the canopy.	A1	Radius: 5.6m. Area: 99 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Good Inspection Limitations: None Bat Habitat:	No action required.	
T06	Horse chestnut (<i>Aesculus hippocastanum</i>)	Tree	Height (m): 12 Stem Diam(mm): 340 Spread (m): 4N, 4E, 4S, 4W Crown Clearance (m): 5 Life Stage: Mature Rem. Contrib.: 20+ Years	Tree located on grass area between car parking spaces. Minor browning and leaf discolouration.	B1	Radius: 4.1m. Area: 53 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Moderate Inspection Limitations: None Bat Habitat:	No action required.	
T07	Horse chestnut (<i>Aesculus hippocastanum</i>)	Tree	Height (m): 11 Stem Diam(mm): 370 Spread (m): 3.5N, 3.5E, 3.5S, 3.5W Crown Clearance (m): 2 Life Stage: Mature Rem. Contrib.: 20+ Years	Tree located on grass area by the vaping shelter. Minor browning and leaf discolouration.	B1	Radius: 4.4m. Area: 61 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Moderate Inspection Limitations: None Bat Habitat:	No action required.	
T08	Sycamore (<i>Acer pseudoplatanus</i>)	Tree	Height (m): 11 Stem Diam(mm): 370 Spread (m): 3N, 3E, 3S, 3W Crown Clearance (m): 3 Life Stage: Semi Mature Rem. Contrib.: 20+ Years	Tree located on grass area by bike shelter. Old pruning wounds from historic crown reduction.	B1	Radius: 4.4m. Area: 61 sq m.		Other Reference: Physiological Condition: Good Structural Condition: Good Distance1: Distance2: You customise: Public Amenity Value: Moderate Inspection Limitations: None Bat Habitat:	No action required.	