

Reassessment is essential when the ground conditions are apparent, and redesign may be necessary in the light of soil conditions found. The responsibility for establishing the soil and sub-soil conditions rests with the contractor.

The image displays three architectural drawings of a building facade and section, including a plan view, a section view, and a detail view. The plan view shows a rectangular building with a central entrance and a large window. The section view shows the building's profile with a central entrance and a large window. The detail view shows a close-up of the entrance area with dimensions and annotations.

Plan View (Left): Shows the building's footprint with dimensions. The overall width is 107, and the depth is 59. The entrance area is 32 wide and 22 deep. The window area is 24 wide and 11 deep. The building is surrounded by a 53 wide area. The entrance is marked with a circle and 'R 7.11'. The window is marked with a circle and 'R 15.11'. The building is surrounded by a 53 wide area. The entrance is marked with a circle and 'R 7.11'. The window is marked with a circle and 'R 15.11'.

Section View (Middle): Shows the building's profile with a central entrance and a large window. The entrance is 21 wide and 8 deep. The window is 21 wide and 8 deep. The building is surrounded by a 21 wide area. The entrance is marked with a circle and 'R 7.11'. The window is marked with a circle and 'R 15.11'.

Detail View (Right): Shows a close-up of the entrance area with dimensions and annotations. The entrance is 32 wide and 22 deep. The window is 24 wide and 11 deep. The building is surrounded by a 53 wide area. The entrance is marked with a circle and 'R 7.11'. The window is marked with a circle and 'R 15.11'.

T2	30.07.26	Scale bar/ North arrow added to drawing	HA
TI	12.06.26	Tender Issue	HA
P1	19.12.25	Condition Discharge	SF
Rev	Date	Description	Initials

TENDER/CONDITION DISCHARGE

DRAWN BY: KG

ADAM ARCHITECTURE

www.adamarchitecture.com contact@adamarchitecture.com