



1.Existing basin (to become fishpond)



3.State of disrepair of the existing basin perimeter wall

- No. Notes
1.

Dimensions to be verified on site. Only figured dimensions to be used and any discrepancies in dimensions are to be reported to the architect. No dimensions are to be scaled from printed drawings. Any areas indicated on this drawing are for guidance only. No responsibility is taken for their accuracy.
2.

There is a risk of injury or death in construction if the works are not properly planned and supervised. The contractor must not undertake any element of the work without first having carried out the necessary risk assessments and prepared detailed method statements.

* Initial Release	01/07/26
no. revision.	date.

BLDA ARCHITECTS

RIBA
Chartered Practice

211 Design Centre East
Chelsea Harbour
London, SW10 0XF

mail@blda.co.uk
www.blda.co.uk
t +44 (0) 20 7838 5555
f +44 (0) 20 7838 5556

Job: TH - Walled Garden Landscaping

Title: Photos of existing basin

Type: 700 Component		
Status: FOR INFORMATION		
drawn by MF	checked by -	approved by -
scale NTS @ A1	size A1	date 02/07/26
job number	drawing number	revision
3125	759.3	*