Rood Ashton Hall, Weston Ashton, BA14 6AS

1. A general view of the courtyard to east:

2. South elevation showing the original fountain:

3. West elevation with raised terrace and outdoor seating:

4. Steps up to terrace at side of entrance archway:

5. The restored well in the north east corner of the courtyard:

6. Part of the north elevation:

7. Central planter:

8. Entrance doors in arched opening to north:

9. The gully at the centre of the courtyard:

10. Damaged cobbles replaced with concrete infill:

11. Sunken area of cobbles and showing some cobbles which have partially disintegrated:

12. The fountain in detail: