





- KEY**
- Underground gas services
 - Underground foul water
 - Underground unknown services
 - Underground CATV services
 - Existing drainage
 - Pedestrian access route
- From main entrance and car park
 - Existing stone post and coping
 - Existing stone wall and coping
 - Low-level brick wall
 - Basement access stair
 - Existing close boarded timber fence
 - Existing timber gate
 - Existing drainage
 - Existing Cabana structure
 - Existing gravel path
 - Existing hard surface
 - Existing grass
 - Existing entrance to Spa
 - Existing ramped access